Indiana Inspection Copies

ROUTLIN:	·				
Please initia	l and date:	•			
JC 10-9-90	Jim Coleman	NPDES NUMBER IN 0032425			
12/10/10	Eu #2 (Jim Filippini)	Facility Name <u>VSS LEAD REFININ</u>			
PO 10/10	Belinda (for routing to States & Permits)	City Name <u>EAST Chicago</u> , IN			
	Ken tenny (for tracking & distribution to assignee)	Inspection Date 9-20-90			
EU #2 Staff a	ssignee <u>Bah Tal</u> Recip				
# of Copies	N	ame: date sent: 10/10/90			
	Joan (if	ilippini Karnauskas Bio Inspection) ridges			
	(if B	io Inspection) hief sends to State) / 6/90 LAO, IDEM			

Reference #43

01

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION V CENTRAL DISTRICT OFFICE 536 SOUTH CLARK STREET CHICAGO, ILLINOIS 60605

DATE: SEP 2 8 1990

SUBJECT: Reconnaissance Inspection Report, USS Lead Refining,

East Chicago, Indiana (IN0032425)(AFE108:8A)(AFE103:FH)

FROM: John J. Mc Guire, Environmental Engineer

Central District Office (5CDO)

TO: Michael Mikulka, Chief

Compliance Section (5WCC)

THRU: Willie H. Harris, Chief Central District. Permit Related Issues Central District Office (5CDO)

On September 20, 1990, I conducted a reconnaissances inspection at the subject facility in response to Water Division's request for inspections for FY '90. Mr. Richard Liscum, General Manager, represented the facility and supplied the information for this report. Form 3560-3 attached.

USS Lead refining stopped production on December 13, 1985. Samples were continued to be collected from the facility discharge until July 15, 1987, at which time electrical power was disconnectied.

Mr. Liscum stated that there had been a light rain on September 18th and also, there was some rain over the previous weekend (Sept. 15-16). I observed the discharge point to the canal. There was no flow coming out of the discharge pipe into the discharge structure located at the canal. There was noticeable oil in this structure. Along the side of the canal there are a number of oil storage tanks. There is a large growth of vegetation near the mouth of the structure.

I also looked at the old discharge point near the slag piles. Mr. Liscum stated that this pipe had been filled with cement. The area around the old discharge point was heavily overgrown with vegetation. There was no discharge observed.

Mr. Liscum informed me that records concerning this facility were destroyed when there was a fire in the main office building in May of 1990.

If you have any questions concerning this report please call me at 353-2704.

Attachments Form 3560-3

. •	• • •					
SEPA NE		s Environmental P Yeshington, D. C. :		tion Report	1	Form Approved OMB No. 2040-0003
	<u> </u>	on A: National				Approval Expires 7-31-85
ansaction Code 1M 25 3IMOC	NPDES 32 42 5 11	12/9/01/019/21	1201	Inspection Type 7 18 A	inspect	or Fac Type 202
		Remarks.			111	
Reserved Facility Evaluation 7 7 7 7		BI 0 12/2 72/2	4	73 74 75		80
		Section B: Fac	lity Data			
me and Location of Facility In 155 Lead Ref. ning, 300 Kennely Ave.	Inc.			Entry Time W AM [9/05 Exit Time/Date		Permit Effective Date Permit Expiration Date
Fest Chicago, In	1 46312			9.45 AM/9-	20-80	I britist commission batte
ime(s) of On-Site Representative(s	;}	Title(s)				Phone No(s)
Richard Liscom		Gener	al H	Nanager		
ame, Address of Responsible Official Title					<u> </u>	
		Phone No),	 		Consected Yes No
		C: Areas Evalu				
Permit	(S * Satisfactory, N			ectory, N = Not Evaluated) retreatment		Operations & Maintenance
Records/Reports	Laboratory		<u> </u>	ompliance Schedules	\vdash	Studge Disposal
Facility Site Review	Effluent/Rece			elf-Monitoring Program		Other:
Sec	tion D: Summary of F	indings/Comm	ents (Atta	ch additional sheets if nece	ssery)	
my{s),and Signature(s) of Inspecto	Or(s) Age	ncy/Office/Tele	phone		10	810
amals) and Signaturels; of Inspector Mills Mills	U		=	12) 353-2704	1	9/28/90
_						
gnature of Reviewer	Age	ncy/Office				
John	•	•	- ي	sp lens		9128/90
		Regulatory Of	fice Use	Only		

ation Taken

Compliance Status

Noncompliance
Compliance

Date